

JAYCOMMAND

powered by  **BM PRO**

POWERING YOUR ADVENTURES.


HELP GUIDE

AUTO HITCH HEIGHT


JAYCOMMAND
powered by 



CONTROLLER



NODE



APP



SWITCH

SYSTEM COMPONENTS

Auto Hitch Height Button on LCI mini Touch pad not functioning?

This may occur when trying to initiate the auto hitch height feature from outside mini touch pad using BM PRO firmware 1.3.3 and earlier.

1. Update the APP to update the firmware
2. The firmware will be available on the 10/24/19
3. Follow the Help guide, **Updating the JAYCOMMAND App, Firmware & BYOD**



BM PRO
821 E. Windsor Ave, Unit 1
Elkhart, IN 46514
service@teambmpro.com